

Menu

HISTORY FILE MAP for year 2004

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

343.07:56-08:51 55m 1024bps real-time data lost due to antenna subreflector problems at DSS-24, also causing the uplink to be aborted. DR G105043 refers.

346.12:15-12:17 2m 1024bps real-time data lost during 4096bps playback (346:06:21-06:34) when DSS-24 antenna halted resulted in 13m lost recorded 512bps. DR G105054 refers. DSS-26 acquired telemetry early to minimize data loss.



345.04:14-04:21 7m 1024bps real-time data lost during 4096bps playback a telemetry processor problem at (344:23:50-345:00:17) DSS-54 resulted in 27m lost recorded 512bps. DR M102924 refers.

348.14:52-16:52 1h 56m 1024bps & 6m 512bps real-time data lost when DSS-24 was released early to support Image since they lost a dump pass because of DSS-34 lightning strike.